


电机平键需用螺钉加垫片紧固，防止平键掉出； A-A
垫片外径需小于电机轴径



LHSG-58-XXX-RDP-22-58-110-145-M8

Harmonic Reducer

HONPINE